



Wiring SpeedoMaster _1 > RallyeMaster-Systems

Rallyemaster

Sensor

brown + 5VDC	>	brown +
blue signal	>	green-yellow signal
green-yellow	>	blue -

Please mount without any pressure at the wire.