



Wiring SpeedoMaster_2 > RallyeMaster-Systems

RallyeMaster		Sensor
brown + 5VDC	>	red +
blue signal	>	blue signal
green-yellow	>	black -

Please mount without any pressure at the wire.