



Wiring TurnMaster > RallyMaster-Systemes

RallyMaster

brown + 5VDC
blue signal
green-yellow

>
>
>

Sensor

brown +
blue
green-yellow -